## Screw conveyor

# البريمة

# **Tube Screw Conveyor**

### (Tube screw conveyor)

Used to transport raw materials horizontally and in a relatively diagonal way.

It is a cylinder with a rotating helix inside.

It has a circular maintenance hole at the top.

It is characterized by accuracy, so it is used in the case of the need for stability and high accuracy in feeding.

Usually used in medium and small capacities.

Its life span is comparatively less than that of the aquarium screw conveyor.

### بريمة اسطوانية


تستعمل في نقل الخامات بشكل أفقى وبشكل مائل نسبياً.


عبارة عن أسطوانة داخلها حلزونة دوارة.


لها فتحة صيانة دائرية في الأعلى.

تتميز بالدقة لذلك تستخدم في حالة الحاجة لدقة عالية في التغذية.

> تستخدم عادة في القدرات المتوسطة والصغيرة. عمرها الأفتراضي أقل نسبياً من البريمة الحوض.







41